

Cultured Marble Restoration



Worn, Cracked, Scratched, Burned, cultured marble vanity tops can be completely restored. Our revolutionary ***Euro-Satin***™ treatment makes old vanity tops look like the new solid surfaces that can cost ten times as much. An ugly, cracked, stained bowl can be replaced without removing the vanity top. The new bowl will never get cracks around the drain from aging like the old one. Your vanity tops will look great and be easy to maintain! **Nothing Else Like It Anywhere, At Any Price! No Paint, No Spray, No Odors, and It's Ready To Use The Same Day!**

Ceramic Tile & Grout Restored



NO Paint NO Liner NO Dust
NO Odors NO Mess NO Down Time

READY TO USE THE SAME DAY!

Discount Coupons Available On-Line (See web site for details*)

Limited Lifetime Warranty (See web site for details*)

SPR® ***Surface Restoration***

Local Authorized ***SPR***® Dealer

WWW.SPR SVC.COM

UGLY

EMBARRASSING BATHTUB?™



Restore The Original Look & Safety To Your UGLY Bathtub At A Fraction Of Replacement Cost!



NO PAINT, NO ODORS, NO SPRAYING

Restored Tub Includes A Factory-Like Slip Resistant Surface

SPR® ***Surface Restoration***

"Lifetime Warranty, Will Never Peel" *



"Since 1973"

What Causes A Bathtub To Become Ugly, Stained, & Hard To Clean?

All water contains minerals. Most bathtub stains are caused by these: mineral deposits, dirt, bath and body oils, even shampoo and hair rinse residues adhere to the tubs surface.

As these deposits continue to build up most people look for a strong cleanser to remove them. Over time, harsh cleansers erode the tubs glassy smooth surface, making minerals



and residues even more difficult to remove. As the tub becomes harder to clean most people just look for a stronger cleaner. **Stronger cleaners only make matters worse since they erode the surface even more, making it extremely ROUGH, UGLY, and HARD TO CLEAN.** All bathtub manufacturers warn against the use of abrasives, acids, and strong alkali cleansers. Any of these products used on a new bathtub voids the warranty. At one time, **expensive bathtub replacement** was the only solution to the **UGLY TUB** problem.



UGLY, UNSIGHTLY, PEELING PAINT

A Better Solution! In the early 1970's **professional bathtub refinishing** started to become popular. Since the mid 1980's hundreds of would-be bathtub refinishers have sprung up worldwide. **These would-be refinishers have been doing nothing more than painting bathtubs. The ongoing results have been DISASTROUS!**

PEELING PAINT has become synonymous with **bathtub refinishing** since practically every bathtub painted in the last 25 years has peeled like a banana. Virtually all painted tubs, even the best of the best, finally peel! In addition, conventional bathtub coatings (paints) are extremely hazardous and flammable.

The immediate results of bathtub refinishing look pretty good, but when it starts to peel like this tub (bottom left) it looks worse than it did before it was painted!

The New Generation Of Bathtub Restoration

SPR Bathtub Refinishing® opened its doors in 1973 repairing and refinishing damaged porcelain and fiberglass tubs. In 1978 we introduced **The New Generation of Tub Restoration**, the world's only professional **NO Paint, NO Spray, NO Odor, NO Hazard** bathtub restoration process! We call it **PTR**®, which is short for **Poly Tub Restoration**™.

This highly guarded trade-secret process and all of its components are unlike any other bathtub refinishing process in the world. Our trade-secret process and the unique products



PAINT BEING STRIPPED OFF TUB

to perform it are available only through our worldwide network of independent dealers. If the tub has been painted all paint must be stripped in order to administer the trade secret treatment and restore a like new look.

WORLD'S ONLY LIFETIME GUARANTEE AGAINST PEELING



A Like New Look Without Paint, Odors, or Mess

Ready To Use The Same day

Every Tub Is Custom Fitted With Factory-Like Safety Bottom.

A Combination of Beauty & Safety At A Reasonable Cost!